

MONUMENT RECORD

Corner I.D. #

E-19

STATE OF INDIANA - COUNTY OF MONROE

Section Thirty (30), Township 9 North, Range 1 East

Monument Description & Remarks: Found 5/8" Rebar w/aluminum cap @ East 1/4
corner of section. Rebar was firm in ground; 0.2' out of ground; cap
somewhat damaged. Cap reads "Gene W. Darnall LS 1749".

Recovery Tie Drawing

PK nail @ base,
SW side 21" Smooth
Bark Hickory.
Survey marker sign
set SE face, 4.7'
above ground.

Old fencing,
woven wire & barbed wire

5/8" Rebar
w/cap

N 23° W
2.42'


S 76° W
27.52'

Old barb wire fence

PK nail North
side, 0.5' up,
12" Shagbark
Hickory

PK nail West side
0.5' up, 11" Smooth
Bark Hickory

Old fencing, woven
wire & barb wire



● At Corner



Not To Scale

State of Indiana

County of Monroe

Space
Reserved For
Recording
Officer

I, Michael W. Friley, County Surveyor, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 4th day of June, 1996 A.D.

Indiana Registered Land Surveyor No. _____ or

Monroe County Surveyor's Office

United States Government Agency

Monroe County Surveyor

Title

Field Book:

96-01

Page:

57-58